

Canada Product Recall

Hydro-Gear is recalling certain hydrostatic transaxles used in Cub Cadet riding mowers due to injury risk to the operator. Consumers should stop using the product immediately.

Hydro-Gear has identified a limited number of transaxles manufactured late in 2010 whose drive gear may fail causing the drive system to lose the ability to brake effectively, posing an injury risk to the consumer.

Consumers that have mowers with these suspect transaxles should stop using the product immediately and arrange to replace the transaxle.

Identify if your riding mower and transaxle are in the recall range.

STEP 1


Tractor Identification
(see tables for affected models)



Mower Brand 1a

Mower Type 1b

Label Example



DOM (date of manufacture). 1c


Model Number: 1d

Located under seat

STEP 2

Transaxle Identification

(see tables for affected models)



Step 1.
Identify the mower

Step 2.
Identify the transaxle

1a	1b	1c	1d	-	2a	2b
Mower Brand	Mower Type	DOM	Mower Model No.	Retailer	Transaxle Part. No	Transaxle Serial No. (1 st four digits)
Cub Cadet	LTX1142	01/2011-02/2011	13AX91AS596	Cub Cadet Dealers	618-0319	0333 thru 0348
	1142SE	02/2011	13AP91AS596			
	1146	02/2011	13AP91AT596			
Cub Cadet	SLTX1054	03/2011	13WK92AK010	Cub Cadet Dealers	618-04270B	0333 thru 0348

STEP 3-Contact an authorized service provider to arrange a service appointment for a free transaxle replacement

Cub Cadet Riding Mowers- Contact your local Cub Cadet dealer for a free replacement of the transaxle. You can find your local Cub Cadet dealer by visiting their website at www.cubcadet.com or call 1-888-848-6038 between 8 a.m. and 5 p.m. EST, Monday through Friday.