

USA Product Recall

Hydro-Gear is recalling certain hydrostatic transaxles used in Troy-Bilt riding mowers due to injury risk to the operator. Consumers should stop using the product immediately.

Hydro-Gear has identified a limited number of transaxles manufactured late in 2010 whose drive gear may fail causing the drive system to lose the ability to brake effectively, posing an injury risk to the consumer.

Consumers that have mowers with these suspect transaxles should stop using the product immediately and arrange to replace the transaxle.

Identify if your riding mower and transaxle are in the recall range.

STEP 1

Tractor Identification

(see tables for affected models)



Mower Brand

1a

Mower Type

1b



Date of
manufacture
(DOM)


1c

Model Number:

1d

Located under seat

Label Example



STEP 2

Transaxle Identification
(see tables for affected models)

2a Part No.

2b Serial No.

Step 1.
Identify the mower

Step 2.
Identify the transaxle

1a	1b	1c	1d	-	2a	2b
Mower Brand	Mower Type	DOM	Mower Model No.	Retailer	Transaxle Part No.	Transaxle Serial No. (1 st four digits)
Troy-Bilt	Big Red TB2450	01/2011	13WQ92KP066	Troy-Bilt Dealers	618-04270B	0333 thru 0348

STEP 3-Contact an authorized service provider to arrange a service appointment for a free transaxle replacement

Troy-Bilt Riding Mowers- Contact your local Troy-Bilt dealer for a free replacement of the transaxle. You can find your local Troy-Bilt dealer by visiting their website at www.troybilt.com or call 1-888-848-6038 between 8 a.m. and 5 p.m. EST, Monday through Friday.